RECEIVED DIES Error Lienal Properties By Carol Day at 12:51 phr., Jan 20, 2010



MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

CMI INTOXILYZER 5000 MAINTENANCE REPORT

TOCATION OF INSTRUMENT (STREET AND CATY) Charlack PD, 8401 Midland Bivd. Charlack, Mo. 63114 Charlack PD, 8401 Midland Bivd. Charlack, Mo. 63114 22:26 CHECKLIST Place a chock (✓) to the felt of each item if found to be salisfactory or if operating within established limits. (Write in or whole we determined.) Unchecked flame must be corrected before using Instrument. DVM TEST: (350 ± 1.60) _ 366 PD DIAGNOSTIC CHECK (PRINTOUT ATTACHED) OK TIME AND DATE 2:26 01/12/2010 CALIBRATION CHECK And three tests using a standard solution. All three tests must be within ± 5% of the standard value and a have a appraed of .005 or less. Check the box corresponding to the standard solution being used. (USE CAL. CHE MODE) (PRINTOUT ATTACHED) DIAGNOSTIC CHECK And three tests using a standard solution. All three tests must be within ± 5% of the standard value and a have a spread of .005 or less. Check the box corresponding to the standard solution being used. (USE CAL. CHE MODE) (PRINTOUT ATTACHED) DIAGNOSTIC CHECK OLIGAN STANDARD— MUST READ BETWEEN 0.098% AND 0,105% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1 0.099% TEST 2 0.098% TEST 3 0.099% DIAGNOSTIC CHECK PREPORTING THE TEST (PRINTOUT ATTACHED) OK NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH STANDARD AND ADDRESS (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 0.04 0 .05-08 0 .10-14 1 .15-18 1 Over .19 0 BISTURALS 0 0.040 0 .05-08 0 .10-14 1 .15-18 1 Over .19 0 SETURALS 0 0.040 0 .05-08 0 .10-14 1 .15-18 1 Over .19 0 SETURALS 0 0.040 0 .05-08 0 .10-14 1 .15-18 1 Over .19 0 DISTRIBUTION OF THE CONTROLLOWS (DO NOT INCLUDE SIMULATOR TESTS) EXPLICATION OF THE CONTROLLOWS (DO NOT INCLUDE SIMULATOR TESTS) EXPLICATION OF THE CONTROLLOWS (DO NOT INCLUDE SIMULATOR TESTS) PROBLEM TABLES (SO CHECKE THE CONTROLLOWS (CONTROLLOWS (CONTROLLOWS CONTROLLOWS (CONTROLLOWS CONTROLLOWS (CONTROLLOWS CONTROLLOWS CONTROLLOWS (CONTROLLOWS CONTROL	66002343	SN .			glusi'lu qebartud	DAYE	OF INSPECTIO	Ni .	
CHECKLIST Place a chock (✓) to the left of each item if found to be satisfactory or if operating within established limits. (Write in o values where determined) Unchecked liems must be corrected before using instrument. DVM TEST: (.350 ± .160)366 DIDIAGNOSTIC CHECK (PRINTOUT ATTACHED) QK PRINT TEST (PRINTOUT ATTACHED) QK PRINT TEST (PRINTOUT ATTACHED) QK CHARACTER DISPLAY TEST QK PRINT TEST (PRINTOUT ATTACHED) QK CHARACTER DISPLAY TEST QK PRINT TEST (PRINTOUT ATTACHED) QK CHARACTER DISPLAY TEST QK MODE) (PRINTOUT ATTACHED) QK CHARACTER DISPLAY TEST QK And three lests must be within ± 5% of the standard value and a have a spread of .005 or less. Check the box corresponding to the standard solution being used. (USE CAL. CHI MODE) (PRINTOUT ATTACHED) QL 0.000% STANDARD — MUST READ BETWEEN 0.085% AND 0.105% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.085% AND 0.105% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) BEST 1 0.097% TEST 2 0.098% TEST 3 0.099% PERFORM RFI TEST (PRINTOUT ATTACHED) QK NUMBER OF REFUSALS, SINGE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 0.04 0 .05.08 0 .10.14 1 .15.19 1	LOCATION OF INST	AUMENT (STREET AND CA	וָאַן			01/1	12/2010		
Place a chock (✓) to the left of each item if found to be satisfactory or if operating within established limits. (Write in o values where determined.) Unchecked items must be corrected before using instrument. ☑ DVM TEST: (350 ± .160), 356 ☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED) OK. ☑ CHARACTER DISPLAY TEST CK. ☑ PRINT TEST (PRINTOUT ATTACHED) OK. ☑ TIME AND DATE 22:26 01/12/2010 ☑ CALIBRATION CHECK — Run three lests using a stendard solution. All three lests must be within ± 5% of the stendard value and a have a spread of, 055 or less. Check the box corresponding to the stendard solution being used. (USE CAL. CHI MODE) (PRINTOUT ATTACHED). ☑ 0.100% STANDARD — MUST READ BETWEEN 0.095% AND 0.165% INCLUSIVE ☐ 0.000% STANDARD — MUST READ BETWEEN 0.095% AND 0.042% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.095% AND 0.042% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.095% AND 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1 0.097%	Charlack PD		22:26						
## DVM TEST: (,350 ± .160)366 ## DIAGNOSTIC CHECK (PRINTOUT ATTACHED) OK ## CHARACTER DISPLAY TEST OK ## PRINT TEST (PRINTOUT ATTACHED) OK ## PRINT TEST (PRINTOUT ATTACHED) OK ## CALIBRATION CHECK (— Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and in have a spread of .005 or lass. Check the box corresponding to the standard solution being used. (USE CAL. CHI MODE) (PRINTOUT ATTACHED) ## OLOGO% STANDARD — MUST READ BETWEEN 0.085% AND 0,105% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.095% AND 0.042% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.098% AND 0,042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) ## OLOGO% STANDARD — MUST READ BETWEEN 0.098% TEST 3	Place a check	//\ \n \n \(\n \)							
☐ CHARACTER DISPLAY TEST OK ☐ PRINT TEST (PRINTOUT ATTACHED) OK ☐ TIME AND DATE 22:26 01/12/2010 ☐ CALIBRATION CHECK — Run three lests using a standard sotulion. All three tests must be within ± 5% of the standard value and in have a spread of .005 or less. Check the box corresponding to the standard cultion being used. (USE CAL. CHI MODE) (PRINTOUT ATTACHED) ☐ 0.040% STANDARD — MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.039% AND 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1	values where o	letermined.) Unche ST: (.350 ± .150) .3	Z Z			operating wit Instrument	hin establi	ished limits. (W	iri(e in obse
MODE PRINT TEST (PRINTOUT ATTACHED) OK CALIBRATION CHECK — Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and nave a spread of .05 or less. Check the box corresponding to the standard solution being used. (USE CAL. CHI MODE) (PRINTOUT ATTACHED) JO .100% STANDARD — MUST READ BETWEEN .0.055% AND .0.105% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN .0.059% AND .0.105% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN .0.039% AND .0.012% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) SET 1	🗹 DIAGNO	stic Check (Prii	NTOUT ATTAC	нер) <u>Ох</u>	ζ				
☑ TIME AND DATE 22:26 01/12/2010 ② CALIBRATION CHECK — Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and in have a spread of .005 or less. Check the box corresponding to the standard solution being used. (USE CAL. CHI MODE) (PRINTOUT ATTACHED) ☑ 0.109% STANDARD — MUST READ BETWEEN 0.095% AND 0,105% INCLUSIVE ☐ 0.040% STANDARD— MUST READ BETWEEN 0.038% AND 0,042% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.038% AND 0,042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1 ☑ 0.097% TEST 2	Ø CHARAC	TER DISPLAY TES	T <u>OK</u>		 -	· ~			
CALIBRATION CHECK— Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and nave a spread of .005 or less. Check the box corresponding to the standard solution being used. (USE GAL. CHI MODE) (PRINTOUT ATTACHED) 20 0.100% STANDARD—MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0.040% STANDARD—MUST READ BETWEEN 0.038% AND 0.042% (NOLUSIVE (ONLY ONE STANDARD)—MUST READ BETWEEN 0.038% AND 0.042% (NOLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1 0.097% TEST 2 0.098% TEST 3 0.099% 21 SIMULATOR TEMPERATURE (34° ± .2°C) 34 Degrees C 22 PERFORM RFI YEST (PRINTOUT ATTACHED) OK 23 NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 004 0 .0509 0 .1014 1 .1519 1 Over .19 0 .181 any new parts and describe any alterallon or modification that was made to restore the instrument to operate calistactority and with exhibited infinits (use other side if necessary). EPCO. Marketing 0.100% solution Lot# 09001 Bottle# 1144 Expires: 04/22/2011 EPCTING OFFICER PAINT NUMBER/CYCRETIONALS.	PRINT TE	ST (PRINTOUT AT	TTACHED) OK	P b.	~				
Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and nave a spread of .005 or less. Check the box corresponding to the standard solution being used. (USE CAL. CHI MODE) (PRINTOUT ATTACHED) 20.100% STANDARD — MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0.040% STANDARD — MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE (ONLY ONE STANDARD — MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1 0.097% TEST 2 0.098% TEST 5 0.099% EST 1 0.097% TEST 2 0.098% TEST 5 0.099% EST 1 0.097% TEST 2 0.098% TEST 5 0.099% EST 1 0.097% TEST 2 0.098% TEST 5 0.099% FUSH ON THE ST 2 0.098% TEST 5 0.099% FUSH ON THE ST 2 0.098% TEST 5 0.099% FUSH ON THE ST 2 0.099% FUSH ON THE ST 3 0.099% F	☑ TIMÉ VNE	DATE 22:26 01	1/12/2010					<u>. </u>	
MODE) (PRINTOUT ATTACHED) O .100% STANDARD — MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE O .040% STANDARD — MUST READ BETWEEN 0.095% AND 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1 0.097% TEST 2 0.098% TEST 3 0.099% SIMULATOR TEMPERATURE (34° ± .2°C) 34 Degrees C PERFORM RFI TEST (PRINTOUT ATTACHED) OK NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 0-04 0 .0508 0 .1014 1 .1519 1 Over .19 0 Isla any new parts and describe any alteration or modification that was made to restore like instrument to operate salislactority and with stabilished limits (use other side if necessary). PEPCo. Marketing 0.100% solution Lot# 09001 Bottle# 1144 Expires: 04/22/2011 PECTING OFFICER TURE PRINT NUMBER PRINT NUMBER OF SUBJECT BREATH TESTS IN EACH CAST CONTROL OF THE	M CALIBRA	TION CHECK —					 \		.;
MODE) (PRINTOUT ATTACHED) O .0100% STANDARD — MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE OLO40% STANDARD — MUST READ BETWEEN 0.095% AND 0.042% (NCLUSIVE ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) EST 1 0.097%	Hun hava	igniau alagi eenni AAAA lo beeyde B	a slandard so	lulion. All	three lests must	be within ±	5% of the	e standard val	ile and me
☑ 0.100% STANDARD — MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE ☐ 0.040% STANDARD — MUST READ BETWEEN 0.098% AND 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) SET 1 □ 0.097% TEST 2 □ 0.098% TEST 3 □ 0.099% ☑ SIMULATOR TEMPERATURE (34° ± .2°C) 34 Degrees C ☑ PERFORM RFI TEST (PRINTOUT ATTACHED) OK ☑ NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 0.04 0 .05-08 0 .1014 1 .1519 1 Over .19 0 Ist any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactority and with stabilished limits (use other side if necessary). PECO. Marketing 0.100% solution Lot# 09001 Bottle# 1144 Expires: 04/22/2011 PECTING OFFICEN THERET NUMBER PARKET HOLD THE	MQI	DE) (PRINTOUT AT	TTACHEON			a grannstia Rai	intiou pelu	g used. (USE (AL. CHEC
(ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) SET 1 0.097% TEST 2 0.098% TEST 3 0.099% TEST 3 0.099% TEST 3 0.099% TEST 3 0.099% TEST 5 0.	K1 0	.100% STANDARD	- MUST DEAD	N DETIME	=M 0 00000 A LI = -			•	
TEST 2 0.098% TEST 3 0.099% SIMULATOR TEMPERATURE (34° ± .2°C) 34 Degrees C PERFORM RFI YEST (PRINTOUT ATTACHED) OK NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 0-04 0 .0508 0 .1014 1 .1519 1 Over .19 0 .1014 I .1519 1 Over .19 0 .1014 II .1519 1 Over .19 0 .1014 II .1519 1 Over .19 0 .1014 II .1519 II Over .19 0 .1014 II .							SIVE		
SIMULATOR TEMPERATURE (34° ± .2°C) 34 Degrees C PERFORM RFI TEST (PRINTOUT ATTACHED) OK NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 004 0 .0508 0 .1014 1 .1519 1 Over .19 0 .18 any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactority and with extincted calibration PECCING OFFICER TURE PERMIT NUMBER/CENERATION DATE: Det. Bric Sontheimer # 64		- COLE OT AT DAIL		ed per n —	IAINTENANCE R	EPORT)			
SIMULATOR TEMPERATURE (34° ± .2°C) 34 Degrees C PERFORM RFI YEST (PRINTOUT ATTACHED) OK NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH YESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 0.04 0 .05.09 0 .10.14 I .1519 I Over .19 0 let any new parts and describe eny alteration or modification that was made to restore like instrument to operate salisfactority and with stabilished limits (use other side if necessary). Septiment of the instrument of the	ST 1 P	0.097%	TEST 2	// *	0.098%	TEST S	<u> </u>	0.0000	
PERFORM RFI TEST (PRINTOUT ATTACHED) OK NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 004 0 .0509 0 .1014 1 .1519 1 Over .19 0 Ist any new parts and describe any alteration or modification that was made to restore the instrument to operate salisfactority and with stabilished limits (use other side if necessary). Fusic Calibration PECTING OFFICER TURE INC							#	0.0999	0
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 004 0 .0508 0 .1014 1 .1519 1 Over .19 0 Ist any new parts and describe any alteration or modification that was made to restore the instrument to operate salisfactority and with stabilished limits (use other side if necessary). FURCING OFFICER TURE PRINT NAME Det. Bric Sontheimer # 64	MI SIMULATO	R TEMPERATURE	$(34^{\circ} \pm .2^{\circ}C)^{-3}$	4 Degrees	C				
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS) FUSALS 0 004 0 .0508 0 .1014 1 .1519 1 Over .19 0 Ist any new parts and describe any alteration or modification that was made to restore the instrument to operate salisfactority and with stabilished limits (use other side if necessary). FURCING OFFICER TURE PRINT NAME Det. Bric Sontheimer # 64	<i>5</i> 1	RELYEST (DDIAM)	ILIT ATTAQUE	o OK					·
FUSALS 0 004 0 .0509 0 .1014 1 .1519 1 Over .19 0 'stablished ilmits (use other side if necessary). Terified calibration PECTING OFFICER THE PERMIT NUMBER/PERMITION DATE	ヹ PERFO#M /		O I VI I MODEL		······································				
FUSALS 0 004 0 .0509 0 .1014 1 .1519 1 Over .19 0 'stablished ilmits (use other side if necessary). Terified calibration PECTING OFFICER THE PERMIT NUMBER/PERMITION DATE									
let any new parts and describe any alteration or modification that was made to restore the instrument to operate salisfactorily and with stabilished limits (use other side if necessary). SepCo. Marketing 0.100% solution Lot# 09001 Bottle# 1144 Expires: 04/22/2011 PECTING OFFICER TURE PERMIT NUMBER/EXPRAIDNENTS PERMIT NUMBER/EXPRAIDNENTS	Z NUMBER O	F REFUSALS, SING	SE LAST MAINT	TENANCE	REPORT, AND A	UMBER OF S	SUBJECT	BREATH YERY	C IN EVOL
erified calibration Performed Officers Perfo	Z NUMBER O	F REFUSALS, SING	DE LAST MAINT OT INCLUDE S	TENANCE IMULATO	report, and A A tests)	lumber of s	3087ECL	BREATH TEST	8 IN EACH
PECTING OFFICER TURE PERMIT NUMBER/EXPRATIONALS PERMIT NUMBER/EXPRATIONALS PERMIT NUMBER/EXPRATIONALS PERMIT NUMBER/EXPRATIONALS PERMIT NUMBER/EXPRATIONALS	NUMBER OF RANGE AS I	FREFUSALS, SINC FOLLOWS: (DO NO 004 0	:0509	0	10-14	45.40	•		
PECTING OFFICER TURE PERMIT NUMBER/EXPRATIONALES PERMIT NUMBER/EXPRATIONALES PERMIT NUMBER/EXPRATIONALES PERMIT NUMBER/EXPRATIONALES	NUMBER OF RANGE AS I	FREFUSALS, SINC FOLLOWS: (DO NO 004 0	:0509	0	10-14	45.40	•		
PECTING OFFICER TURE 17 C C Det. B) G Y PERMIT NUMBER/EXPRATIONALES PERMIT NUMBER/EXPRATIONALES	FUSALS 0 ist any new parts stablished limits	FREFUSALS, SINC FOLLOWS: (DO NO 004 0 and describe any a use other side if neces	:0509	0	10-14	45.40	•		
PECTING OFFICER TURE 177 C.C. 1967 PERMIT NUMBER/EXPRATIONALE PERMIT NUMBER/EXPRATI	FUSALS 0 ist any new parts stablished limits	FREFUSALS, SINC FOLLOWS: (DO NO 004 0 and describe any a use other side if neces	:0509	0	10-14	45.40	•		
PECTING OFFICER TURE 177 C.C. 1967 PERMIT NUMBER/EXPRATIONALE PERMIT NUMBER/EXPRATI	FUSALS 0 ist any new parts stablished limits	FREFUSALS, SINC FOLLOWS: (DO NO 004 0 and describe any a use other side if neces	:0509	0	10-14	45.40	•		
PECTING OFFICER TURE 197 C C 1967 PERMIT NUMBER/EXPRATIONALE Det. Bric Sontheimer # 64	VI NUMBER OF RANGE AS I	FREFUSALS, SINC FOLLOWS: (DO NO 004 0 and describe any a use other side if neces	:0509	0	10-14	45.40	•		
PECTING OFFICER TURE 177 C.C. 1967 PERMIT NUMBER/EXPRATIONALE PERMIT NUMBER/EXPRATI	FUSALS 0 ist any new parts stablished limits	FREFUSALS, SINC FOLLOWS: (DO NO 004 0 and describe any a use other side if neces	:0509	0	10-14	45.40	•		
PRINT NUMBER/EXPRATION DATE PERMIT NUMBER/EXPRATION DATE PERMIT NUMBER/EXPRATION DATE Det. Bric Sontheimer # 64	V NUMBER OF RANGE AS I	FREFUSALS, SINC FOLLOWS: (DO NO 004 0 s and describe any a luse other side if necession	:05-:09 Iteration or modi essary).	0 Heatlon tha	.1014 I	.1519 ore the Instrum	l nent to oper	Over .19 rate satisfactorily	
PERMIT NUMBER/EXPRATION DATE PERMIT NUMBER/EXPRATION DATE Det. Bric Sontheimer # 64	VI NUMBER OF RANGE AS I	FREFUSALS, SINC FOLLOWS: (DO NO 004 0 s and describe any a luse other side if necession	:05-:09 Iteration or modi essary).	0 Heatlon tha	.1014 I	.1519 ore the Instrum	l nent to oper	Over .19 rate satisfactorily	•
Det. Bric Sontheimer # 64	PO NUMBER OF RANGE AS INTERPOLATION OF PARTIES OF PARTI	FREFUSALS, SING FOLLOWS: (DO No 004 0 s and describe any a luse other side if neces ion ag 0.100% solution	:05-:09 Iteration or modi essary).	0 Heatlon tha	.1014 I	.1519 ore the Instrum	l nent to oper	Over .19 rate satisfactorily	
16 Expires 11/13/2010 TELEPHONE NUMBER	PECTING OFFI	FREFUSALS, SING FOLLOWS: (DO NO O04 O O04	.0509 Iteration or modisessary). ution Lot	0 Heatlon tha	.1014 I	.1519 ore the Instrum Expires:	l nent to ope/ 04/22/201	Over .19 rate satisfactorily	•
	NUMBER OF RANGE AS IN THE PECTING OFFI	FREFUSALS, SING FOLLOWS: (DO NO O04 O O04	.0509 Iteration or modisessary). ution Lot	0 Heatlon tha	.1014 I	ore the Instrum Expires:	1 nent to ope/ 04/22/201	Over .19 rate satisfactority	•
	NUMBER OF RANGE AS IN THE PURALS OF STATE OF STA	FREFUSALS, SING FOLLOWS: (DO NO O04 O O04	lteration or modi	0 Heatlon tha	.1014 I	Expires: (l nent to ope/ 04/22/201 Sontheim	Over .19 rate satisfactority	